FORM	
12-67	2820

Approved Fer Release 2007/03/05 CIA-RDP74B00496R0004000500

	10/15/510.	14	ζ.	_	-	16	-	
4B004 96	R0004000500	D			Û	Ŋ		V

- SEC

T TEE INT Q			(*	men i med m)	i		
8 Jul	Dec 71854	61	REPRO	DUCTION PROHIBIT	ED	ODES 1	12 Days
ACTION	1	DM	6	DORS	11 0	7 16	
	2		7	INTEL	12	17	
	3		8	HASC	13	18	
	4	DSA	9	Con Pul	4/4	19	
	5	RB	1ø	11	15	2ø	

25X1

S E C R E T Ø81139Z DEC 71 CITE

3437

PRIORITY

IDEALIST DM-4

SUBJECT MISSION C-361-C OSCAR SIERRA

- 1. NUMEROUS OSCAR SIERRA ACTIVATIONS WERE NOTED THROUGHOUT MUCH OF THE FLIGHT. PRE AND POST FLIGHT EXAMINATION OF THE O/S IS NORMAL.
- 2. NONE OF THE ACTIVATIONS APPEAR TO BE THE RESULT OF A VALID O/S SIGNAL, NOR DO THE ACTIVATIONS SEEM TO BE CAUSED BY FAULTY WIRING.
- 3. EXAMINATION OF THE "C" RECORDER TAPE REVEALS A NOISE OF UNKNOWN SOURCE APPEARING ON ALL VHF/UHF SYSTEM 17B L/W CHANNELS, 90 THROUGH 1000 MHZ, INCLUDING O/S. THE NOISE PULSE IS BROADBAND, ABOUT 0.5 MS WIDE, RUNNING AT ABOUT 0.75 TO 1.0 MS RATE, AND IS CYCLIC, STEADY FOR ABOUT 16 SECONDS AND QUIET FOR ABOUT 1 SECOND.
- 4. FREQUENT ACTIVATION OF THE O/S QUAD 1 SELECT IS NOTED,
 BUT AT A MUCH MORE FREQUENT INTERVAL THAN "AMBER". QUAD 2 OR 3
 AMBER WILL SHOW WHEN THIS NOISE IS AT A VERY HIGH LEVEL (NEAR TAPE
 SATURATION) TIMES OF Ø45116. Ø459Ø5 AND Ø5Ø436 ARE TYPICAL.



Approved For Release 2007/03/06 CIA RDP74B00496R000400050073-0

CH CHINA

Approved For Release 200 የነδ3/06 - CYA-RDP 74B00499R000400050073-0

FILE INFO		SECR (When Fill	l l		
		REPRODUCTION	PROHIBITED		
ACTION	1	6	11	16	
	2	7	12	17	
	3	8	13	18	
	4	9	14	19	
	5	1ø	15	2ø	

PROBABLY FROM WITH THE ARTICLE. WE DO PLAN A VERY CLOSE LOOK AT THE NEW "H" CONFIG USED ON THIS MISSION AS THE NOISE AND ACTIVATIONS WENT AWAY DURING THE TIME FRAME OF Ø543 TO Ø548 WHEN THE "H" WAS SECURED. REPEATING, THE NOISE SOURCE IS CURRENTLY UNKNOWN. WE JUST HAVE IDEAS WHERE TO LOOK.

S E C R E T

BT